

3000 W HERCULES VACUUM CLEANER



General Info

The optional 3000 W vacuum cleaner has a 100 l internal storage container. The Vacuum cleaner is powered by 3 individual motors.

The way of construction minimizes clogging to optimize the airflow.



Hercules Vacuum cleaner

Compatibility

The 3000W vacuum cleaner can be installed on all new (as of August 2017) three phase 50Hz F-Series Models equipped with a new the router system (as of August 2017). It is recommended to order this unit instead of the Metabo ASR 2050.

Note: Older F1612 units and/or router installations will need an upgrade pack and/or extra power socket (contact our service department for upgrade requirements)

When the Hercules is not connected with an extra socket, the power requirements of the F1612 3 x 400V + N , 50Hz raise from 15A to 20A!

Part Number(s)

- 500-9345: 3000 W Hercules vacuum cleaner for F Series

Maintenance

This vacuum unit will need a regular maintenance every 800 working hours. If damaged a replacement motor can be fitted ([#500-0304] – 1 replacement motor for Hercules)

Warranty

The warranty to F-series partners on the vacuum cleaner is 1 years on parts. The replacement filters, replacement brushes and collection bags [#500-9347] are excluded from this 1 years on parts warranty. These items fall under the consumable warranty. Damage to the motors due to worn brushes isn't covered by the warranty.

Summa nv
Rochesterlaan 6
8470 Gistel
Belgium

Tel. +32 59 27 00 11
Fax. +32 59 27 00 63
Website www.summa.eu

BTW BE0456 536 537
IBAN BE95 7360 2727 5858



Main Specifications

IPC Soteco M1003BAG Hercules

- Air output (at fan): 345m²/h
- Vacuum: 24 KPa
- Filter surface: 35.500 cm²
- Nominal power: 3.000 Watt
- Container volume: 100 l

Summa nv

Rochesterlaan 6
8470 Gistel
Belgium

Tel. +32 59 27 00 11

Fax. +32 59 27 00 63

Website www.summa.eu

BTW BE0456 536 537

IBAN BE95 7360 2727 5858

Consumables & Replacement Parts

Garbage collection bag (5x)	500-9347	
Standard Filter Replacement filter	500-9348	
Carbon Filter replacement	500-9349	
Replacement Motor	500-9351	