
Creating a cut design from an image

- 1. Click onto the New Design Button ^D or go to the **Design** menu **New**.
- 2. Double click onto Laser Effects.

3. Go to the Image Menu – Insert Image. The following form will appear:

The 3 types of images you can import are Tiff, JPEG & BMP.



Double click onto the required image. A small crosshair will appear on the screen. Move your mouse to the top left and single click the left mouse button.

- 4. Go to the Views menu Zoom Resize.
- 5. Go to the **Image** menu **Freeze Images**.
- 6. You may need to use the Zoom tool if the image appears small.
- 7. Select the Draw Line Tool . You are now ready to draw your shape. Here is a list of the drawing tool commands.
 - Left Clicking will enter a line point.
 - Holding Ctrl down and left clicking will enter a curve point.
 - The Tab button closes a shape.
 - The backspace button deletes the last point entered.
 - Entering a point with the 'o' key on your keyboard snaps the next point to a horizontal or vertical line.
- 8. When you have finished using the Drawing tool click the right mouse button twice.
- 9. Go to the **Image** menu **Un-Freeze Images**.
- 10. Click onto the image and press the Delete key on your keyboard. You are now ready to send the design to the cutter.
- 11. Place the material in the machine and set the media area.


Setting the Media Area

Click the Media button on the machine controller and press enter. Move the cutting head using the arrow keys to the bottom left of the material, press enter. Move the cutting head to the top right of the material and press enter again.

- 12. Make sure your machine is on-line by clicking the Hand button on the machine keypad.
- 13. Go to the **Output** menu **Material Manager Delete** and click the delete button.
- 14. Go to the Output menu Material Manager Setup.

15. You now have one of two options.

If your material already exists you can select it from the drop down list.



Select the Output Design button 🔧. Your machine will now cut the drawn shape.

Or

If you have a new material to set-up click the **Setup** button, the select the **Effects** Tab. And Click the New Material button. Enter the name of your new material. Select the OK button.

- 16. Make sure your new material is selected and click the OK button on the Material Manager Properties form.
- 17. Select the Output Design button \blacksquare . To change the power and speed settings for a new material go the Selection **Tab** and **Edit effects.** Double click onto the Effect you wish to change, i.e. Cut -Through and the Edit Material effect form will appear.

up Cuttor - Flat E fects			/	/			
Effects / Materials	Effect Details		/				
* Effects	Effect	1	Arc. Ener	Passes	Velocity	Max Power	Min. Power
8 Materials	Cut-Throu	gh	25	1	ş	5	5
- Master	Engrave Kiss-Cut		22.22	1	ŝ	5	555
Paper	NoCut		1	0	1	5	5
		me Cut/The	Ngh		-	×	
a second	Number of Passes :	0	÷			100	
New Material	Are Error:	25	÷ µn				Copy Effect
Delete Material	Velocity		÷ cn/s				
	Marine Barrow	5	÷.*			×	
Save Ma	Maximum Power:	-	mind .				

- Change your power and speed settings and click the OK button on the first form, then the OK button on the last form and click the Send to Cutter button.
- 19. If you would like to save your design to the database go to the **Design** menu **Save Save as New design in Database** and **OK.**