

Summa nv Rochesterlaan 6 8470 Gistel Belgium

Pinch Roller Replacement

This document describes the procedure to replace the pinch rollers in a Summa series roll cutter.

It is advised to replace both outermost pinch rollers at the same time to ensure a good transport of the media.

Required Tools

Small Flat Screwdriver

Required Parts

Pinch Roller, part number 395-401

Procedure

Protect the base of the machine.









Summa nv Rochesterlaan 6 8470 Gistel Belgium

Remove the clip from the shaft. Use a small screwdriver to pry in the gap of the clip.



Push the shaft out of the pinch roller block.




Remove the pinch roller.





Summa nv Rochesterlaan 6 8470 Gistel Belgium

Insert the new pinch roller and slide the shaft in the pinch roller.



Position the clip on the shaft and push down.



Revised January 4, 2021